

VEHICLE INSPECTION REPORT

Mobile pre-purchase diagnostics · 145 checkpoints · 1in.pt

VEHICLE	YEAR	MILEAGE	VIN
Kia Ceed 1.4	2013	107,000 km	hidden in sample
PLATE	INSPECTION DATE	INSPECTOR	
hidden in sample	09.08.2026	1in.pt · Strong Theory	

VERDICT: NEGOTIATE

Inspector's conclusion

The mileage is genuine — confirmed by the service history and by the condition of the interior and electronics. On the body: resprayed rear bumper and rear right door, a tighter gap on the left after repair. Mechanically healthy; the findings are arguments for negotiating.

2. Body — paint depth readings, µm

Roof	45	factory
Bonnet	52	factory
Front left wing	48	factory
Front right wing	44	factory
Front left door	83	factory
Front right door	104	factory
Rear left door	89	factory
Rear right door	161	resprayed
Rear left wing	96	factory
Rear right wing	108	factory
Tailgate	95	factory
Front bumper	58	factory
Rear bumper	220	resprayed
Left sill	66	factory
Right sill	71	factory
A/B/C pillars left	60	factory
A/B/C pillars right	63	factory

Tyres (detail)

Front axle	Bridgestone, DOT 2020, tread OK
Rear axle	Rottala, DOT 2026, tread OK
Spare wheel	present

Computer diagnostics (OBD)

Launch scanner: no critical codes in any module. The full diagnostic log is sent to the client together with the report.

Service history

Last service ~107,200 km: oil, filters, alternator belt. Service-book records since 2015 (18,803 km) are consistent with the mileage.

Full inspection protocol

✓ — OK · △ — needs attention

1. DOCUMENTS (7)

- | | |
|--|---------------------------------------|
| ✓ VIN matches: docs, body, plate | ✓ Number of owners — 2nd owner |
| ✓ Registration (DUA) — original | ✓ Both key sets present |
| ✓ IPO book — dates, validity | ✓ Theft, lien, restriction check |
| ✓ Service book — records, dealer stamps — records up to ~107,200 km | |

3. BODY — VISUAL (15)

- | | |
|--|--|
| △ Panel gaps — uniformity — smaller on the left | △ Windshield — chips, cracks, replaced — replaced |
| ✓ Repaint signs — orange peel, runs, dust | ✓ Rear glass — defroster, integrity |
| ✓ Color mismatch between panels | ✓ Door seals — paint traces |
| ✓ Weld seams — factory or repair | ✓ Corrosion — sills, arches, underside |
| ✓ Sealant in trunk/hood — factory | ✓ Corrosion — door cavities, trunk lid |
| ✓ Door/hood hinges — removal signs | ✓ Underside — protection, impacts, rust |
| ✓ Fender bolts — unscrewing signs | ✓ Wheel arch liners — presence, mounts |
| ✓ Glass markings — same date/maker | |

4. LIGHTS & GLASS (8)

- | | |
|--|------------------------------|
| ✓ Headlights — markings, date matching | ✓ Turn signals — all working |
| ✓ Headlights — clouding, moisture | ✓ Brake lights — all working |
| ✓ Tail lights — cracks, moisture, replaced | ✓ Reverse light |
| ✓ Fog lights — working | ✓ License plate light |

5. TIRES & WHEELS (9)

- | | |
|--|--|
| △ Tire brand — all 4 matching — mixed brands | ✓ Size matches factory spec |
| △ Tire manufacture date (DOT) — 2020 and 2026 | ✓ Wheels — cracks, deformation, repair |
| ✓ Tread depth — uniformity | ✓ Spare tire — present, pressure |
| ✓ Uneven wear (inner/outer) | ✓ Jack and wrench |
| ✓ Cracks, bulges, sidewall cuts | |

6. INTERIOR (24)

- ✓ Smell — damp, mold, oil, smoke
- ✓ Moisture — under mats, in trunk
- ✓ Steering wheel — material wear
- ✓ Pedals — wear matches mileage?
- ✓ Driver seat — bolster wear
- ✓ Seatbelts — condition, date tag
- ✓ Airbags — indicator, covers intact
- ✓ Headliner — sagging, stains
- ✓ Climate control — all modes
- ✓ A/C — cooling, smell
- ✓ Heater — all fan speeds
- ✓ Power windows — all 4
- ✓ Mirrors — adjust, heat, fold
- ✓ Heated seats (if equipped)
- ✓ Power seat adjust (if equipped)
- ✓ Sunroof — open, close, seal
- ✓ Multimedia — screen, sound, inputs
- ✓ Bluetooth — pairing, hands-free
- ✓ Navigation — working
- ✓ Rearview camera / parking sensors
- ✓ USB/AUX ports
- ✓ 12V socket
- ✓ Central locking — all doors
- ✓ Wipers and washer — all modes

7. UNDER THE HOOD (13)

- ✓ Burnt oil/coolant smell
- ✓ Leaks — oil, coolant, PS, brake
- ✓ Engine oil — level, color, emulsion on cap
- ✓ Coolant — level, color, purity
- ✓ Brake fluid — level, color
- ✓ PS fluid — level
- ✓ Battery — age, terminals, corrosion
- ✓ Timing belt/chain — when replaced
- ✓ Drive belts — cracks, tension
- ✓ Hoses — cracks, clamps, leaks
- ✓ Non-standard repair signs
- ✓ Non-original parts visible
- ✓ VIN on body — legibility, tampering

8. ENGINE START (10)

- ✓ Cold start — first try?
- ✓ Blue smoke (oil)
- ✓ White smoke (coolant)
- ✓ Black smoke (fuel)
- ✓ Unusual noises at start (knock, whistle)
- ✓ Knock persists after warm-up?
- ✓ Idle stability
- ✓ Engine vibration at idle
- ✓ All indicators off after start?
- ✓ Check Engine light — off?

9. OBD DIAGNOSTICS (7)

- ✓ Engine errors — current
- ✓ Engine errors — stored (history)
- ✓ Transmission errors
- ✓ ABS / ESP errors
- ✓ Airbag errors
- ✓ Mileage across ECUs — matches?
- ✓ Live Data — sensors normal

10. TEST DRIVE (18)

- ✓ Auto trans — no delay engaging
- ✓ Auto trans — smooth shifts
- ✓ Auto trans — no jerks or slipping
- ✓ Manual — easy shifting
- ✓ Manual — clutch: travel, bite point
- ✓ Manual — clutch pedal no pulsation
- ✓ Acceleration — no hesitation
- ✓ Steering — play
- ✓ Pulls to one side straight
- ✓ Wanders left-right
- ✓ Vibration at 80-120 km/h
- ✓ Humming at speed (bearings)
- ✓ Brakes — effectiveness
- ✓ Brakes — pedal pulsation
- ✓ Brakes — pulling to side
- ✓ Steering shake when braking
- ✓ Suspension knocks/squeaks on bumps
- ✓ Shock absorbers — body bouncing

11. LIFT INSPECTION (17)

EXTRA · +100 €, by prior arrangement — not part of this inspection

- | | |
|--|-----------------------------------|
| • Underside — corrosion, impacts, protection | • Ball joints — play |
| • Exhaust system — integrity, mounts | • Bushings — cracks, wear |
| • Front brake pads — remaining | • Shock absorbers — leaks |
| • Rear brake pads — remaining | • Springs — sagging, cracks |
| • Brake discs — wear, grooves, cracks | • Stabilizer — links, bushings |
| • Brake hoses | • Subframe — mounts, corrosion |
| • CV joint boots — integrity | • Gearbox — oil leaks |
| • Tie rod ends — play | • Differential / driveshaft (AWD) |
| • Tie rods — condition | |

Inspection photos



This is an anonymised sample of a real report (VIN and plate hidden). Clients receive this PDF right after the inspection — in English, Portuguese or Russian.

Strong Theory Unipessoal LDA · NIPC/VAT: 519 255 780 · PT519255780

Showroom: R. Manuel Henrique, Armazém 2, 2645-550 Alcabideche · Mon–Fri 9:00–19:00, Sat 10:00–17:00

+351 933 033 393 (WhatsApp) · auto@1in.pt · <https://1in.pt>